



Hull Wastewater

Work Order Information

Date: 03/29/2016

Type: Inspections

Status: In Process

Manhole ID: MH 20169

Priority: Normal

Reason: Operational

Description of Issue

Description: Manhole Inspection

Notes:

Actions Taken

Staff: John Currier

Service: Manhole clogged

Photos

